

Executive Offices 2492 River Road New Hope, PA 18938-9519

TEL. (215) 862-5284 FAX (215) 862-7665

FOR IMMEDIATE RELEASE

February 10, 2016

TRAVEL DELAYS POSSIBLE DURING PEAK PERIODS AT I-78 TOLL PLAZA

Phone: (215) 862-7693 or (412) 995-0275

Contact: Joe Donnelly or Ethan Vickers

Collision Destroyed Concrete Protection Barrier for One Toll Booth, Reducing Cash-Payment Capability from Four Lanes to Three Lanes

DUE TO DAMAGE CAUSED BY TUESDAY AFTERNOON TRUCK CRASH

WILLIAMS TOWNSHIP, PA – The Delaware River Joint Toll Bridge Commission today warned cash-paying motorists to anticipate delays – especially during peak travel periods – at the toll plaza for the agency's I-78 Toll Bridge.

One of the toll-collection lanes at the plaza was knocked out of service Tuesday afternoon by tractor trailer driver who has subsequently been charged with reckless driving. The accident remains under investigation by Pennsylvania State Police from that agency's Belfast barracks.

The driver's truck veered into the concrete protection barrier separating two of the plaza toll lanes around 2:20 p.m. yesterday. The collision severed the concrete pediment that is designed to protect toll collectors who handle cash transactions in the immediately adjoining toll booth. The truck sustained damage and had to be towed from the scene. The driver was transported to a nearby hospital shortly after the accident; the Commission does not have any further information regarding his injuries or medical status.

The Commission will not be able to bring the compromised toll lane back online until a new concrete safety barrier can be designed and installed to ensure maximum protection of its toll collectors and electronic toll equipment in the affected lane. This will reduce the toll plaza's operational capacity from four lanes to three lanes for handling cash transactions.

As a result of this situation, westbound I-78 motorists who pay cash tolls at the plaza may encounter traffic congestion and moderate delays during peak traffic periods until the compromised toll lane can be put back into service. The busiest daily commuter traffic period is weekday evenings, roughly 3 p.m. to 7 p.m.

The Commission has examined the barrier toll plaza's overall structural integrity and determined it to be satisfactory to allow the three remaining lanes to stay in service. The Commission is constructing an action plan to repair the damaged toll lane. It's too early in the process to determine when the toll lane may be brought back into service.

The I-78 toll facility (four-lane conventional toll booth plaza with nearby separated two-lane Express E-ZPass structure) is approximately one mile west of the Commission's I-78 Toll Bridge. The facility handles only westbound traffic. It processed slightly more than 32,000 toll transactions a day last year. Of those transactions, nearly 70 percent were handled through E-ZPass – most of which occurred in the segregated Express-E-ZPass facility next to the conventional barrier toll plaza. Express-E-ZPass allows E-ZPass-equipped motorists to pay their tolls while driving at highway speeds.

About the Commission

The Delaware River Joint Toll Bridge Commission was formed by the Commonwealth of Pennsylvania and the State of New Jersey in 1934. It operates seven toll bridges and 13 toll-supported bridges, two of which are pedestrian-only spans. The Commission is a self-supporting public-service agency that receives neither federal nor state tax dollars to finance its projects or operations. Funding for the operations, maintenance and upkeep of its bridges and related transportation facilities is solely derived from revenues collected at its toll bridges. The Commission's jurisdiction extends along the Delaware River from the Philadelphia-Bucks County line north to the New Jersey/New York border. The bridges carried more than 141.7 million cars and trucks in 2015. For more information about the Commission and its various initiatives to deliver safer and more convenient bridge travel for its customers, please see: www.dritbc.org.