

Seidersville Hall – Window Replacement ADDENDUM #1

- Windows #1, #2, #3, #4, #7, #8, #9, #10, #15, #16, #17, #18, #23, #24, #25, #26, #29, #30, #31, #32, #35, #36, #38, #39:

Windows are single-hung windows

Screens to these windows are half-screen

- Windows #5, #6, #19, #27, #28, #37, #40:

Windows are non-operation/static windows

- Windows #36 and #38:

Lower pane of the single-hung window is obstruction glass

- Windows #13, #14, #20, #21, #22, #33, #34, #41, #42:

Windows are double-hung windows

No screens to this windows

- Windows #27 and #28:

These windows are to be replaced with either one or two non-operation/static windows