2540-FM-BWM0131 6/2005



COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WASTE MANAGEMENT P.O. BOX 8472, HARRISBURG, PA 17105-8472

Inspection ID 3340690 & 3340235

Field Code NA

INSPECTION REPORT – MUNICIPAL WASTE LANDFILL

Site I	.D.	<u>25</u>	5 <u>983 </u>	ephone # <u>610-317-</u>	<u> 3200 </u>		
				erator Name <u>Bethlel</u>			
			·	ress 2335 Applebu	tter Ro	oad	
				nlehem, PA 18015			
				inty Northampton			
				District Manager Operations Super	uicor I	Env Compliance Ma	nager
				Environmental Tra		LITY Compliance wa	<u>iiagei</u>
			# PF 268729 SF 266826	<u>Liviloiiiioitai Tie</u>	117100		
			Additional eFACTS: 3334998, 3340232		***************************************		
			Date: 03/22/22 & 3/31/22 Type: RTNC Re	esults: OUTNO	F	Resolved: / /	
-				ated: 6		· · · · · · · · · · · · · · · · · · ·	800
			1 - No Violation Observed 2 - Not-Applicable 3 - N	ot-Determined 4	- Non	-Compliance	
STA	TL	IS			-	CHAPTER	LINE
1 2	3	4	REVISION	COMM ATTA	CHED	CITATION	ITEM
			GENERAL PROVISIONS				
			Required insurance in effect (expiration date 08/01/2022			271.371	1
][>		Operation in accordance with approved plans and permit.			273.201(c)(2)	2
			Operation within permit boundaries (vertical and horizontal)		273.201(c)(2)	3	
	IC		Disposal Timing and sequence as per Section 273.112(1).		273.201(c)(2)	4	
			No unapproved wastes or liquids.	273.201(d)-(m)	5		
			Isolation distances are adhered to.	273.202(a)	6		
			Facilities certification requirements followed.			273.203(a), (b)	7
			Written Department approval of new construction prior to w	aste disposal.		273.203(c)	8
			DAILY OPERATIONS				
			Proper signs posted.			273.211(a)	9
			Site perimeter clearly marked and grid coordinate system i	n use.		273.311(b)-(d)	10
			Proper barriers installed around site and access controlle not present.	ed when attendant		273.212(a)-(i)	11
			Access roads maintained and negotiable by collection vehi	cles.		273.213(a)-(i)	12
X C			Approved means of measuring and inspected waste utilize	d.	\boxtimes	273.214(a), (b)	13
			Adequate equipment on-site and stand-by equipment avail	able.		273.215(a), (b)	14
	ם כ		Vehicles directed promptly to unloading area and promptly	unloaded.		273.216(a), (b)	15
\boxtimes			Solid waste spread and compacted as approved by Dep permit.	artment as part of		273.216(c)	16
	בוב	3 -	Operator implements fugitive air contaminant control/meas and controls air pollution including no exceeding of a standards, no open burning, and minimizing generatio emissions from facility.	mbient air quality	\boxtimes	273.217(a)	17
][>	 □	Operator complies with Air Quality Plan approval and Air Permit.	quality Operating		273.217(b)	18
		11 - 3	2 2 0 8 E			_	

Sapoooooooo

Bethlehem Landfill Company 100020 3/22/22 & 3/31/22

INSPECTION REPORT - MUNICIPAL WASTE LANDFILL (Cont'd)

ST	Δ	T1 19	S	1 - No violation Observed 2 - Not-Applicable 3 - Not-Determined 4 -		Compliance	
1 2	3.5	3		GENERAL REQUIREMENTS COMM		CHAPTER CITATION	LINE
				DAILY OPERATIONS (Cont'd)			
	ᆀ			Operator does not cause or allow attraction, harborage, or breeding of vector.		273.218(a)	19
		\boxtimes		Operator implements nuisance minimization and control plan.	\boxtimes	273.218(b)(1)	20
ØC				Operator performs regular, frequent, and comprehensive site inspections to reduce potential for offsite odors.		273.218(b)(2)	21
		X		Operator promptly addresses and correct problems and deficiencies discovered during inspections.	\boxtimes	273.218(b)(3)	22
		\boxtimes		Operator implements nuisance minimization and control plan to minimize and control other conditions harmful to the environment or public health, or which create safety hazards, odors, dirt, noise, unsightliness and other public nuisances.	\boxtimes	273.218(c)	23
× C				Operator does not receive solid waste at a landfill in excess of the maximum or average daily volume approved in the permit.	\boxtimes	273.221(a)	24
$\boxtimes \square$				Operator implements radiation protection action plan.	\boxtimes	273.223(a)	25
				Operator monitors incoming waste in accordance with Department's guidance or in a manner at least as protective of the environment, facility staff and public health and safety.	\boxtimes	273.223(b)	26
	ןכ			Radiation detector elements shall be as close as practical to wasteload and in appropriate geometry to monitor the waste.	\boxtimes	273.223(c)	27
	J			Operator has portable radiation monitors capable of determining the dose rate and presence of contamination of a vehicle that has caused an alarm. Upon exceedance of alarm level, a radiological survey of the vehicle is performed.	\boxtimes	273.223(d)	28
				Operator notifies Department immediately and isolates vehicle when radiation dose rates are exceeded.	\boxtimes	273.223(e)	29
\boxtimes]			Monitoring equipment is calibrated at frequency specified by manufacturer, but not less than once a year.	\boxtimes	273.223(f)	30
				If radioactive material is detected, vehicle containing material shall not leave facility without written Department approval and an authorized federal Department of Transportation exemption form.		273.223(g)	31
]			Uniform cover of the approved daily cover material is placed on exposed solid waste at the end of each working day or at the end of every 24 hours, whichever interval is less.		273.232(a)	32
\boxtimes				If intermediate cover requires revegetation, it is established within 30 days.		273.233(e)	33
⊠ [Slopes constructed during daily landfilling and intermediate cover activities may not exceed 50 percent.		273.233(f)	34
				Operator does not cause or allow waste pollution within or outside the site from operation of the facility.		273.241(a)-(c)	35
	X]			Operator has restored or replaced adversely affected water supply with an alternative source of like quantity and quality.		273.245(a)	36
	☒			Temporary water supply is provided within 48 hours.		273.245(b)	37
	X]			Permanent water supply is provided within 90 days.		273.245(c)	38
\boxtimes				No waste 15 feet of inside top of the lined perimeter berm.		273.252(e)	39

Bethlehem Landfill Company 100020 3/22/22 & 3/31/22

INSPECTION REPORT - MUNICIPAL WASTE LANDFILL (Cont'd)

120.0000	11.55	1 7.1	 1 - No Violation Observed 2 - Not-Applicable 3 - Not-Determined 4 -	Non-	Compliance	
ST/			GENERAL REQUIREMENTS GITAG		CHAPTER CITATION	LINE ITEM
	T		DAILY OPERATIONS (Continued)	,		
			Lined perimeter berm 4 ft. high constructed and maintained along edge of the lined disposal area.		273.252(f)	40
	וֹב		Edge of liner clearly marked.		273.252(g)	41
	1		Alternate leachate recirculation method may be used if approved if one of the liner systems is a composite liner.		273.274(b)	42
			Underground pipes used to transport leachate to leachate storage impoundments or tanks equipped with secondary containment or comply with 245.445.		273.275(g)	43
	3 C		Operator isolates coal seams, coal outcrops and coal refuse from waste deposits to prevent combustion of waste and damage to liner.		273.291(a)	44
][Mine openings within site sealed as approved by Department.		273.291(b)	45
	3 [Operator implements plan for controlling potential damage from subsidence submitted and approved under 273.120.		273.291(c)	46
][X]	Landfill designed, constructed, maintained and operated to prevent and minimize potential for fire, explosion, or release of solid waste constituents into air, water, or soil of the Commonwealth.		273.301	47
			Emergency equipment including portable fire extinguishers, fire control equipment, spill control equipment, and decontamination equipment available. For fire equipment requiring water, facility has a water supply of or adequate quantity and pressure to supply the equipment.		273.302(a)	48
][\Box	Emergency equipment tested and maintained.		273.302(c)	49
$\boxtimes \Box$)[Adequate space maintained to allow unobstructed movement of emergency personnel and equipment.		273.302(d)	50
$\boxtimes L$][Litter controlled/collected and barriers/fences in place.		273.220(a)-(c)	51
			COVER/SLOPES/REVEGETATION			
		X	Daily/intermediate cover meets performance and design requirements.		273.232(b), 273.233(b), (c)	52
⊠ [JL		Minimum 5-day supply of daily and intermediate cover maintained on-site.		273.232(c) & 273.233(d)	53
\boxtimes			Intermediate cover applied within time limits.		273.233(a)	54
$\boxtimes L$][Intermediate slopes do not exceed 50%.		273.232(d)	55
ØL][Cap placed over entire surface of final lift meets performance standards.		273.234(a)(1)	56
		X	Final cover meets performance and design requirements; applied within time limits.	\boxtimes	273.234(b)-(e)	57
\boxtimes			Final slopes stable and erosion controlled.		273.234(f)	58
\boxtimes			Final slopes graded 3-15% or terraced to 33% as approved.		273.234(g)	59
			Minimum revegetation and successful revegetation requirements adhered to.		273.235(a)-(e) & 273.236(a), (b)	60
			WATER QUALITY PROTECTION			
\boxtimes			Surface and groundwater treatment facilities properly operated and maintained.		273.241(b)	61
		X	Surface water percolation minimized/prevented.	\boxtimes	273.242(b)(1) & 273.234(e)(4)	62

Bethlehem Landfill Company 100020 3/22/22 & 3/31/22

INSPECTION REPORT - MUNICIPAL WASTE LANDFILL (Cont'd)

	e e e			MAN A		and white
		TU 3	GENERAL REQUIREMENTS COMM		CHAPTER CITATION	LINE ITEM
\boxtimes			Soil erosion and sedimentation controls designed and implemented as per approved plans; gullies over nine inches repaired.		273.242(a)-(c)	63
\boxtimes			Sedimentation ponds and discharge structures designed, constructed, operated, and maintained in accordance with Chapters 273, 102, and 105.		273.243(a)-(g) & 273.244	64
			LINER SYSTEM			
\boxtimes			Liner system designed, constructed, operated, and maintained when required.		273.251(a), (b)	65
\boxtimes			Edge of liner requirements adhered to (i.e., no waste within 25 feet if adjacent liner, 4 feet high lined berm, to prevent lateral escape of leachate, adequate spacing on inside of berm to collect stormwater and sediment).		273.252(d)	66
\boxtimes			Leachate detection zone monitored weekly.		273.255(c)	67
\boxtimes			Protective cover protects primary liner and leachate collection system and allows free flow of leachate into the collection system.		273.257(a)	68
M			Protective cover meets minimum requirements and at least 18 inches thick.		273.257(b)	69
\boxtimes			Leachate collection system within protective cover meets minimum requirements.		273.258(a), (b)	70
\boxtimes			Barrier designed, constructed and maintained as required to prevent lateral migration of leachate off-site in surface mined areas.		273.259(a)-(d)	71
\boxtimes			8 feet of select waste placed over protective cover.		273.260	73
			LEACHATE TREATMENT			
図			Leachate collected and handled through Department approved method(s).		273.272(a)-(c)	74
\boxtimes			Leachate transportation requirements adhered to.		273.273(a)-(c)	75
\boxtimes			Cessation of site operation if alternate leachate handling not available.		273.273(d)	76
	\boxtimes		Leachate treatment system permitted and fully operational at least 3 years before closure.		273.273(e)	77
	\boxtimes		Leachate recirculation in accordance with regulations.		273.274(1)-(4)	78
×			Leachate collection and storage systems on-site have capacity of 30 days or 250,000 gallons, whichever is greater.		273.275(a)-(f)	79
Ø			Leachate flow rate measured daily; analyzed quarterly.	\boxtimes	273.276(a)-(b)	80
Ø			Department notified when remedial action(s) required.		273.277(1)-(4)	81
			WATER QUALITY MONITORING			
Ø			Approved monitoring system installed and maintained.		273.281(a), (b) & 273.283	82
\boxtimes			Quarterly and annual monitoring requirements adhered to and results submitted Department within time constraints.		273.284 & 273.285	83
\boxtimes			Groundwater assessment plan submitted and implement as required.		273.286(a)-(g)	84
\boxtimes			Groundwater abatement plan submitted and implemented as required.		273.287(a)-(f)	85
			RECORDKEEPING AND REPORTING			
			Operational records maintained, available and submitted as required.		273.288 & 273.311- 273.313	86
\boxtimes			Daily Operational Records kept in accordance with regulations for the life of the facility bond or longer if necessary.		273.311(d)	87

Bethlehem Landfill Company

100020 3/22/22 & 3/31/22

INSPECTION REPORT - MUNICIPAL WASTE LANDFILL (Cont'd)

			ं	1-No violation observed 2-Not-Applicable 0-Not-Determined 4-	WWSIR		i assessasi
ST/ 1 2		ՄՏ 3 4		GENERAL REQUIREMENTS COMM		CHAPTER CITATION	LINE
$\boxtimes \Box$				Operator submits quarterly operation report.	\boxtimes	273.312	88
				Operator submits annual operation report with fee.		273.313	89
				MINERALS AND GAS			
] [2	<u>a</u> [Gas venting and monitoring in accordance with approved plans.		273.292(a)-(d)	90
][2	3		Combustible gas levels not exceeded.		273.292(e)	91
	J	3		Forced gas venting if required.		273.292(f)	92
]Σ	3 [Gas recovery conducted as per approved plan and §273.293, including annual analysis.		273.293(a), (b)	93
				EMERGENCY PROCEDURES			
][Contingency plan implemented if there is an emergency.		273.303(a)-(c)	94
				RECYCLING			
				Operator shall salvage and recycle waste in accord with recycling plan. (273.196)		273.331(a)	95
				Salvaging and recycling controlled by operator and prevents interference within operations and prevents health hazardous nuisance.		273.331(b)	96
$\boxtimes \Box$][Salvaged materials stored in an approved area or transported offsite.		273.331(c)	97
$\boxtimes \Box$				Drop off center established for at least three recyclables.		273.332(a)	98
				Drop off center properly located, contains bins or containers, open at least 8 hours per week and 4 hours during evenings or weekends.		273.332(b), (c)	99
$\boxtimes \Box$][Approved public notice of availability of drop off center availability is provided.	\boxtimes	273.332(d)	100
$\boxtimes \Box$][On or before January 15 each year, operator informs municipality in writing of weight and type of materials recycled previous year.		273.332(e)	101
				SPECIAL HANDLING AND RESIDUAL WASTES			
				Special handling and residual wastes disposed with prior Department approval, and in accordance with permit and Chapter 273.		273.501	102
	f]	Infectious waste disposal restrictions adhered to.		273.511(a)-(d)	103
][Chemotherapeutic waste disposal restrictions adhered to.		273.512	104
	- 1			Sewage sludge co-disposal and monofill requirements followed.		273.513	105
				Sewage sludge sampling requirements adhered to and sludge meets standards for control of pathogens, vectors, and odors.		273.513(c)	106
				Disposal of municipal waste incineration ash in landfill or landfill cell that meets Chapter 273 requirements.		273.514(a)	107
				Ash residue disposal in dedicated landfill or landfill cell unless co-disposal in accordance with Chapter 273 (including leachability treatment).		273.514(b)	108
			\Box	Ash residue covered immediately or as approved by the Department.		273.514(c)	109

Site Name **ID Number** Bethlehem Landfill Company

100020 3/22/22 & 3/31/22 Date

INSPECTION REPORT – MUNICIPAL WASTE LANDFILL (Cont'd)

CHAPTER CITATION Comments ATTACHED COMMENTS ATTACHED COMMENTS ATTACHED	LINE
⊠ □ □ □ Bond filed with Department. 271.312 Bond maintained in an amount and with guarantees as required. 271.333(b) Bond amount \$	ITEM
Bond maintained in an amount and with guarantees as required. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercia	
Bond maintained in an amount and with guarantees as required. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Description of a commercia	110
Proof of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Policy #HDOG72482547	111
as specified by 271.374. Policy #HDOG72482547 271.374 Insurer (company name) ACE American Insurance Company Expiration Date: 8/1/2022	
Insurer (company name) ACE American Insurance Company Expiration Date: 8/1/2022	
Expiration Date: 8/1/2022	112
	-



COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WASTE MANAGEMENT

INSPECTION REPORT COMMENTS

Date of Inspection	03/22/2022	2	Identification Number	100020
Company/Facility/Sit	te Name	Bethlehem Landfill Com	pany	

Comments:

The PA Department of Environmental Protection ("Department") conducted a routine complete inspection on March 22, 2022 at Bethlehem Landfill Company ("BLC"). Representing the Department from the Solid Waste Program was Mathew Vipond ("this inspector"). Phillip Garcia and Cody White provided the site tour and met with this inspector at the conclusion of the inspection. Weather was sunny, 46°, winds northwest at 10-15 MPH, 36% humidity.

The following department personnel have entered the landfill since the February 17, 2022 inspection: Matt Glogowski (02/22/2022); Chris Madden (03/01/2022).

3/22/2022 SITE TOUR:

Prior to entering the landfill, this inspector conducted an odor patrol in the areas surrounding the landfill. A slight, intermittent garbage odor was detected approximately 1000 feet east of the landfill entrance, adjacent to the unloading of solid waste. No other offsite odor was detected.

No excessive dust or mud was observed on Applebutter Road near the entrance to the facility.

All signage was clearly posted at the entrance.

This inspector entered the landfill at 0932 hours.

Trucks were observed queuing at the truck wash for cleaning. One truck was bypassing the wash. The wheels on this truck were free of mud and debris.

All roads were drivable and properly graded. The water truck had recently sprayed the road to the upper deck and no dust from vehicles was occurring.

BLC is continuing to operate the working face at SE2-AB Phase I at the eastern end of the landfill, on the upper deck. Heavy equipment operations were pushing waste downhill onto the slope for disposal. Two compactors and one dozer were grading waste inside the active fill area. Multiple litter fences were staged on the upper deck to trap windblown litter. Due to high winds some litter was pushing past the fencing downslope. Mr. Garcia contacted his picking crew to immediately come out and clean this area. BLC's perimeter line misters were not in operation, due to winter weather. BLC is using a tarp for daily cover.

Some downslope rutting of biosolids intermediate cover material on north slope was observed. Discussed observation with Mr. Garcia who stated that dozer tracking for mixing of cover material had created the ruts which would be corrected. BLC is reminded honor the requirements of §273.242(b)(1) by applying cover soil uniformly to maximize stormwater runoff and minimize surface water percolation into the solid waste.

Some intermediate cover on east/northeast slopes showed daylighting of waste and windblown plastic litter. BLC is reminded to honor the requirements of §273.233(1) and ensure that waste is properly covered to prevent vectors, odors, blowing litter and other nuisances.

On the south side of the landfill, grading and foundation work is still being implemented by third-party contractor for the future LFG/energy plant.

Sedimentation pond #4 was observed and is partially cleaned out. Operator has contracted with third-party consultant to begin work in the spring. (NOTE: At the subsequent routine-partial inspection conducted on 3/31/2022, work had begun on the cleanout and regrading of the pond).

BLC's flare was in operation, with a temperature of 1651°F and a flow rate of 3129 cfm.

The scalehouse was calibrated on January 11, 2022.

3/31/22 SITE TOUR:

On 3/31/22, in response to an odor complaint, this inspector conducted an odor patrol adjacent to the landfill. Slight intermittent and moderate persistent odors of mulch were detected throughout Steel City. This inspector met with Operations Supervisor, Phillip Garcia, to discuss findings. Mr. Garcia stated that no fertilizer or sludge had been accepted by the landfill in the recent past. Mr. Garcia escorted this inspector on a driveraound tour of the landfill. No odors consistent with the mulch odors in Steel City were detected.

ODOR COMPLAINT INVESTIGATIONS:

The department received two odor complaints since the last inspection on February 17, 2022. Complaints were followed up with odor patrols conducted by the Department on 2/28/22, 3/7/22, 3/16/22, 3/22/22 and 3/31/22 as well as a routine partial inspection conducted on 3/31/22 as a follow-up to the odor complaint received the same day.

Line item #13: Overweight truck logs revealed the following number of overweight trucks: February: 35

Line item #17: BLC's odor patrol logs, gas data and site inspection logs were reviewed. Since the last inspection, BLC conducted 16 odor patrols. BLC's odor patrols and odor patrol measures appear to be following their Nuisance Minimization and Control Plan.

Line item #24: Daily tonnages were reviewed from February 17 through March 21. There did not appear to be any exceedances of the 1800-ton daily limit. The greatest one-day tonnages were:

February 21: 1792 tons March 8: 1792 tons

Line item #25-31: Daily radiation monitor checks were reviewed since the last inspection. Records appeared complete. BLC has had the following radiation hits since the February 17 inspection:

3/22/22: I-131, disposed on site.

Line item 52: BLC is reminded to maintain intermediate cover in accordance with the performance standards in 25 Pa. Code § 273.233(a)(1)(5). "Uniform and compacted intermediate cover shall... prevent vectors, odors, blowing litter and other nuisances; control infiltration of precipitation and erosion and sedimentation."

Line item #57: A Notice of Violation was issued to BLC on 4/29/20 for a violation of 25 Pa. Code § 273.234(b). BLC has responded to the Notice of Violation, however the violation remains outstanding.

Line item #80: Leachate flow rates: February: 746,009 gallons

Line item #88: The guarterly operation report was submitted on 1/27/22.

Line item #100: Public notice of recycling was published in the Morning Call on Friday, March 25, Saturday, March 26 and Sunday, March 27.

This concludes this inspection report.

Person Interviewed	Sent to Facility via Email	Date	04-01-2022
1 CIBOTI INCIVIOU	(Signature)		04-01-2022
Inspector	Mathew Vipond	Date	04-01-2022
	(Signature)		

Investigator: トレー・ソートでもり Date: 3/22/22
Weather Conditions: 46° アーW NW 15t4 PH 367 H SUDNY

CASE: BLO

ODOR PATROL SURVEY

	0					
	0					
	6	•				4
	6	//	ح	82:6	なり、たい	>
	6	5	کر	4:24	1.11 RD.	(j)
(6	2	ح	9.21	hoffer Teli-	及
のいれるなながれていている。		H	30	9:21	iebutter Rl.	Ž Ž
		لخ	ک	7:17	ower Saucon Ave.	ان در
		5	-ر	H;172		から
		5	مر	9:07	,	Dist.
		مح	الم	9766	•	[\
		W	N	13:05	•	120
		N	ر	9,04	Thews Ave.	Hat
		&	3	9:03	des Ave.	SAY
		Z S	5	4:03	Rharts Ave.	32
		Ž	ع	7:61	Saven Ale.	Sar
		メ	A	9:00	versile Or.	N.
O = Other (describe) COMMENTS & OBSERVATIONS		I = Intermittent N = None	SL = Slight N = None	TIME	SURVEY LOCATION	1 0
G = Garbage S = Sewage		- E	S = Strong M = Moderate			
DESCRIPTION EG = Rotten Egg EF acts #: 3334998 LFG = Landfil Gas			ODOR		•	- 10. 10.

Page ______ of ____

Investigator: ハリアのハカ Date: 3/31/22
Weather Conditions: 529 36024 Winds S/5の i3/484, 82つよ

CASE: BLC Awwey
ODOR PATROL SURVEY

SURVEY LOCATION	TI M E	ODOR INTERSITY S = Strong M = Moderate SL = Slight N = None	ODOR DURATION P = Persistent 1 = Intermittent N = None	EG = Rotten Egg LFG = Landfill Gas G = Garbage S = Sewage D = Dredge O = Other (describe)	eFacts#: 3340232 COMMENTS & OBSERVATIONS
	b4:01	ک	ک		
	02:01	ح	7		
	10,53	لع	ی		
	45 191	SU	Н	0	(sarthy, rulch)
0	12:56	٤	ک.		
	10:58	٤	ح		
Johnston Ive.	10:50	75	H	0	(featilizer, rentch)
Underwas Aire	10,12	٤	2		
Schwab Ave.	(1:12	ک	٤		
	11:13	ጂ	کـ		
Pivers: Le Dr.	1(:14	Σ.	to	0	(anima) banese, where
Redigion Pd.	11:20	75	2		
Lines Saveautie	11:23	کہ	2		
, 	11:24	٨	کے		

Bethlehem Landfill ODOR COMPLAINT LOG (2335 Applebutter Rd, Bethlehem, PA 18015)

			Weather	Weather Data (Allentown (KABE)	WIT (KABE)			Gas M	Gas Management Data		Date of lawis Addressed in last	databased in lace
Date Time	Address	Landfill (miles)	Skies	Temperature	Temperature: Wind (out of)	Residence / Drive-b	Residence / Drive-by Description / Notes	Flare (scfm) BRE (scfm) Total (scfm) Response	BRE (scfm)	Total (scfm)	Response	Report Dated
01/07/22 8:38	Johnston Ave., Steel City	0.980	Mostly Cloudy	26.0	₩ @ 6mph	Residence	Landfill odor on their property to the point where it's nauseating to be outside today.	2959	a	2959	1/10/2022	1/5/2022
01/13/22 8:30	Jefferson Ave, Steel City	0.939	Cloudy	27.0	ENE @ 3mph	Residence	Odor complaint	3048	0	3048	1/18/2022	1/5/2022
01/27/22 5:33	Riverside Drive, Bothlehem	1.270	Fair	7.0	Calm	Residence	I've smelled leachate coming from the landfill. It's putrid.	2916	0	2916	1/31/2022	2/17/2022
02/13/22 21:20	Saucon Ave, Steel City	0.883	Fair	23.0	N @ 12mph	Residence	Odor complaint-light methane gas odor coming from Bethlehem Landfill	3025	0	3025	3025 2/14/2022	2/17/2022
03/05/22 23:44	Saucon Ave, Steel City	0.883	Fair	37.0	E@3 mph	Residence	Landfill gas odor, very strong as always				3/7/2022	3/22/2022
03/31/22 9:13	Johnston Ave., Steel City	0.980	Cloudy	46.0	ENE @ 6mph	Residence	Manure type odor on property that is coming from the Bethlehem Landfill. Odor present at time of call.	}			3/31/2022	3/22/2022

Faulch, Amy

From:

Cody White <Cody.White@WasteConnections.com>

Sent:

Tuesday, March 22, 2022 2:05 PM

To:

Vipond, Mathew

Subject:

[External] FW: Feb 17 to March 21

ATTENTION: This email message is from an external sender. Do not open links or attachments from unknown sources. To report suspicious email, forward the message as an attachment to CWOPA SPAM@pa.gov.

Matt,

I believe this is the last piece of the puzzle for your inspection. If you need anything else just let me know.

Cheers,

Cody White

Environmental Compliance Manager Bethlehem Landfill – Eastern Region

Office: 610.317.3200 ext. 108 Work Cell: 610.390,5536

Email: cody.white@wasteconnections.com



From: Dee Raisner <dee.raisner@wasteconnections.com>

Sent: Tuesday, March 22, 2022 12:33 PM

To: Cody White <Cody.White@WasteConnections.com>

Subject: Feb 17 to March 21

17-Feb	1,662.78	1-Mar	1,677.07
18-Feb	1,111.82	2-Mar	1,627.32
19-Feb	596.32	3-Mar	1,461.74
21-Feb	1,792.32	4-Mar	1,771.60
22-Feb	1,713.82	5-Mar	930.67
23-Feb	1,779.27	7-Mar	1,697.46
24-Feb	1,610.46	8-Mar	1,791.60
25-Feb	927.32	9-Mar	1,712.54
26-Feb	602.17	10-Mar	1,530.45
28-Feb	1,777.15	11-Mar	1,633.56
		12-Mar	488.86
		14-Mar	1,499.19
		15-Mar	1,672.37
		16-Mar	1,776.39
		17-Mar	1,651.47
		18-Mar	1,726.53
		19-Mar	814.47



Dee Raisner Bethlehem Landfill Company Phone: 484-241-4544

dee.raisner@wasteconnections.com



Office: 610-317-3200 Office Fax: 484-626-0600

2335 Applebutter Road Bethlehem, PA 18015 www.bethlehemlandfill.com

File Distribution:

PA DEP NERO WM File-thru M. Vipond
Facility-sent via Email PDF
Lower Saucon Township- sent via Email PDF
R. Bellas/D. Ritter (email PDF)
A. Faulch (email PDF)
AQ: C. Madden/M. Bardzilouskas (e-mail PDF)
M. Glogowski (e-mail PDF)
R. Malizia (email PDF)

Lower Saucon Township: Leslie Huhn manager@lowersaucontownship.org