2540-FM-BWM0131 6/2005

COMMONV
COMMONV
DEPARTMENT O
BUREAU

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF WASTE MANAGEMENT
P.O. BOX 8472, HARRISBURG, PA 17105-8472

Inspection 3388879	
Field Code NA	

INSPECTION REPORT – MUNICIPAL WASTE LANDFILL

Site Add Bet Mur Res Per Insp eFA Cor	Na res nlel nici spo sor coec CT mm	her pal nsi nsi tor S I ent	e <u>E</u> 233 m, F ity ble ten <u>M</u> D #	35 Applebutter RoadAddress 2335 APA 18015Bethlehem, PA 1Lower Saucon TownshipCounty NorthamOfficial Astor LawsonTitle District Mar	Bethlehem L pplebutter Re 8015 pton nager Manager, En ntal Trainee TNO F	Resolved: _05/25/20 x. Daily Volume: _	22			
ST	AT	ับร	3			CHAPTER	LINE			
1	2	3	4	REVISION	COMMENTS ATTACHED	CITATION	ITEM			
				GENERAL PROVISIONS						
\boxtimes				Required insurance in effect (expiration date <u>08/01/2022</u>		271.371	1			
\boxtimes				Operation in accordance with approved plans and permit.		273.201(c)(2)	2			
\boxtimes				Operation within permit boundaries (vertical and horizontal).		273.201(c)(2)	3			
\boxtimes				Disposal Timing and sequence as per Section 273.112(1).		273.201(c)(2)	4			
\boxtimes										
\boxtimes			Isolation distances are adhered to. 273.202(a) 6							
\boxtimes				Facilities certification requirements followed.		273.203(a), (b)	7			
\boxtimes				Written Department approval of new construction prior to waste disposa	l. 🗌	273.203(c)	8			
				DAILY OPERATIONS						
\boxtimes				Proper signs posted.		273.211(a)	9			
\boxtimes				Site perimeter clearly marked and grid coordinate system in use.		273.311(b)-(d)	10			
\boxtimes				Proper barriers installed around site and access controlled when atte not present.	ndant 🔲	273.212(a)-(i)	11			
\boxtimes				Access roads maintained and negotiable by collection vehicles.		273.213(a)-(i)	12			
\boxtimes				Approved means of measuring and inspected waste utilized.	\boxtimes	273.214(a), (b)	13			
\boxtimes				Adequate equipment on-site and stand-by equipment available.		273.215(a), (b)	14			
\boxtimes				Vehicles directed promptly to unloading area and promptly unloaded.		273.216(a), (b)	15			
\boxtimes				Solid waste spread and compacted as approved by Department as part of permit.						
Operator implements fugitive air contaminant control/measures and prevents and controls air pollution including no exceeding of ambient air quality standards, no open burning, and minimizing generation of fugitive dust emissions from facility.							17			
	emissions from facility. Operator complies with Air Quality Plan approval and Air quality Operating Permit.									

Bethlehem Landfill Company
100020
6/28/2022

INSPECTION REPORT - MUNICIPAL WASTE LANDFILL (Cont'd)

ST	Α-	ΓUS	s	1 - No violation Observed 2 - Not-Applicable 3 - Not-Determined 4 -		CUAPTER	LINE
1 2	-	3			MENTS	CHAPTER CITATION	ITEM
	1			DAILY OPERATIONS (Cont'd)			
$\boxtimes \Box$				Operator does not cause or allow attraction, harborage, or breeding of vector.		273.218(a)	19
		X		Operator implements nuisance minimization and control plan.	\boxtimes	273.218(b)(1)	20
				Operator performs regular, frequent, and comprehensive site inspections to reduce potential for offsite odors.	\boxtimes	273.218(b)(2)	21
				Operator promptly addresses and correct problems and deficiencies discovered during inspections.		273.218(b)(3)	22
		\boxtimes		Operator implements nuisance minimization and control plan to minimize and control other conditions harmful to the environment or public health, or which create safety hazards, odors, dirt, noise, unsightliness and other public nuisances.	\boxtimes	273.218(c)	23
$\boxtimes \Box$				Operator does not receive solid waste at a landfill in excess of the maximum or average daily volume approved in the permit.	\boxtimes	273.221(a)	24
$\boxtimes \Box$				Operator implements radiation protection action plan.	\boxtimes	273.223(a)	25
				Operator monitors incoming waste in accordance with Department's guidance or in a manner at least as protective of the environment, facility staff and public health and safety.	\boxtimes	273.223(b)	26
				Radiation detector elements shall be as close as practical to wasteload and in appropriate geometry to monitor the waste.		273.223(c)	27
				Operator has portable radiation monitors capable of determining the dose rate and presence of contamination of a vehicle that has caused an alarm. Upon exceedance of alarm level, a radiological survey of the vehicle is performed.	273.223(d)	28	
				Operator notifies Department immediately and isolates vehicle when radiation dose rates are exceeded.	\boxtimes	273.223(e)	29
				Monitoring equipment is calibrated at frequency specified by manufacturer, but not less than once a year.	\boxtimes	273.223(f)	30
				If radioactive material is detected, vehicle containing material shall not leave facility without written Department approval and an authorized federal Department of Transportation exemption form.		273.223(g)	31
				Uniform cover of the approved daily cover material is placed on exposed solid waste at the end of each working day or at the end of every 24 hours, whichever interval is less.		273.232(a)	32
				If intermediate cover requires revegetation, it is established within 30 days.		273.233(e)	33
				Slopes constructed during daily landfilling and intermediate cover activities may not exceed 50 percent.	273.233(f)	34	
				Operator does not cause or allow waste pollution within or outside the site from operation of the facility.		273.241(a)-(c)	35
	3			Operator has restored or replaced adversely affected water supply with an alternative source of like quantity and quality.		273.245(a)	36
\vdash	◁			Temporary water supply is provided within 48 hours.		273.245(b)	37
	X]			Permanent water supply is provided within 90 days.		273.245(c)	38
\boxtimes				No waste 15 feet of inside top of the lined perimeter berm.		273.252(e)	39

Bethlehem Landfill Company 100020 6/28/2022

INSPECTION REPORT - MUNICIPAL WASTE LANDFILL (Cont'd)

s	TA	TU	s		CHAPTER	LINE				
1	2	3	4	GENERAL REQUIREMENTS COMM	CITATION	ITEM				
				DAILY OPERATIONS (Continued)						
\boxtimes				Lined perimeter berm 4 ft. high constructed and maintained along edge of the lined disposal area.	273.252(f)	40				
\boxtimes				Edge of liner clearly marked.		273.252(g)	41			
	\boxtimes			Alternate leachate recirculation method may be used if approved if one of the liner systems is a composite liner.		273.274(b)	42			
\boxtimes				Underground pipes used to transport leachate to leachate storage impoundments or tanks equipped with secondary containment or comply with 245.445.		273.275(g)	43			
	\boxtimes			Operator isolates coal seams, coal outcrops and coal refuse from waste deposits to prevent combustion of waste and damage to liner.		273.291(a)	44			
	\boxtimes			Mine openings within site sealed as approved by Department.		273.291(b)	45			
	\boxtimes			Operator implements plan for controlling potential damage from subsidence submitted and approved under 273.120.		273.291(c)	46			
		\boxtimes		Landfill designed, constructed, maintained and operated to prevent and minimize potential for fire, explosion, or release of solid waste constituents into air, water, or soil of the Commonwealth.		273.301	47			
\boxtimes				Emergency equipment including portable fire extinguishers, fire control equipment, spill control equipment, and decontamination equipment available. For fire equipment requiring water, facility has a water supply of or adequate quantity and pressure to supply the equipment.		273.302(a)	48			
\boxtimes				Emergency equipment tested and maintained.		273.302(c)	49			
\boxtimes				Adequate space maintained to allow unobstructed movement of emergency personnel and equipment.		273.302(d)	50			
		\boxtimes		Litter controlled/collected and barriers/fences in place.	\boxtimes	273.220(a)-(c)	51			
				COVER/SLOPES/REVEGETATION						
\boxtimes				Daily/intermediate cover meets performance and design requirements.		273.232(b), 273.233(b), (c)	52			
\boxtimes				Minimum 5-day supply of daily and intermediate cover maintained on-site.		273.232(c) & 273.233(d)	53			
\boxtimes				Intermediate cover applied within time limits.		273.233(a)	54			
\boxtimes				Intermediate slopes do not exceed 50%.		273.232(d)	55			
\boxtimes				Cap placed over entire surface of final lift meets performance standards.		273.234(a)(1)	56			
		\boxtimes		Final cover meets performance and design requirements; applied within time limits.	\boxtimes	273.234(b)-(e)	57			
\boxtimes				Final slopes stable and erosion controlled.		273.234(f)	58			
\boxtimes				Final slopes graded 3-15% or terraced to 33% as approved.		273.234(g)	59			
\boxtimes				Minimum revegetation and successful revegetation requirements adhered to.		273.235(a)-(e) & 273.236(a), (b)	60			
				WATER QUALITY PROTECTION						
\boxtimes				Surface and groundwater treatment facilities properly operated and maintained.		273.241(b)	61			
\boxtimes				Surface water percolation minimized/prevented. 273.242(b)(1) 273.234(e)(4)						

Bethlehem Landfill Company 100020 6/28/2022

INSPECTION REPORT - MUNICIPAL WASTE LANDFILL (Cont'd)

S	TA	TU	s		CHAPTER	LINE	
1	2	3	4	GENERAL REQUIREMENTS COMM		CITATION	ITEM
\boxtimes				Soil erosion and sedimentation controls designed and implemented as per approved plans; gullies over nine inches repaired.		273.242(a)-(c)	63
\boxtimes				Sedimentation ponds and discharge structures designed, constructed, operated, and maintained in accordance with Chapters 273, 102, and 105.		273.243(a)-(g) & 273.244	64
				LINER SYSTEM			
\boxtimes				Liner system designed, constructed, operated, and maintained when required.		273.251(a), (b)	65
\boxtimes				Edge of liner requirements adhered to (i.e., no waste within 25 feet if adjacent liner, 4 feet high lined berm, to prevent lateral escape of leachate, adequate spacing on inside of berm to collect stormwater and sediment).		273.252(d)	66
\boxtimes				Leachate detection zone monitored weekly.		273.255(c)	67
\boxtimes				Protective cover protects primary liner and leachate collection system and allows free flow of leachate into the collection system.		273.257(a)	68
\boxtimes				Protective cover meets minimum requirements and at least 18 inches thick.		273.257(b)	69
\boxtimes				Leachate collection system within protective cover meets minimum requirements.		273.258(a), (b)	70
\boxtimes				Barrier designed, constructed and maintained as required to prevent lateral migration of leachate off-site in surface mined areas.	273.259(a)-(d)	71	
\boxtimes				8 feet of select waste placed over protective cover.		273.260	73
				LEACHATE TREATMENT			
\boxtimes				Leachate collected and handled through Department approved method(s).		273.272(a)-(c)	74
\boxtimes				Leachate transportation requirements adhered to.		273.273(a)-(c)	75
\boxtimes				Cessation of site operation if alternate leachate handling not available.	-	273.273(d)	76
	\boxtimes			Leachate treatment system permitted and fully operational at least 3 years before closure.		273.273(e)	77
	\boxtimes			Leachate recirculation in accordance with regulations.		273.274(1)-(4)	78
\boxtimes				Leachate collection and storage systems on-site have capacity of 30 days or 250,000 gallons, whichever is greater.		273.275(a)-(f)	79
\boxtimes				Leachate flow rate measured daily; analyzed quarterly.	\boxtimes	273.276(a)-(b)	80
\boxtimes				Department notified when remedial action(s) required.		273.277(1)-(4)	81
				WATER QUALITY MONITORING			
\boxtimes				Approved monitoring system installed and maintained.		273.281(a), (b) & 273.283	82
\boxtimes				Quarterly and annual monitoring requirements adhered to and results submitted Department within time constraints.		273.284 & 273.285	83
\boxtimes				Groundwater assessment plan submitted and implement as required.		273.286(a)-(g)	84
\boxtimes				Groundwater abatement plan submitted and implemented as required.	273.287(a)-(f)	85	
				RECORDKEEPING AND REPORTING			
\boxtimes				Operational records maintained, available and submitted as required.		273.288 & 273.311- 273.313	86
\boxtimes				Daily Operational Records kept in accordance with regulations for the life of the facility bond or longer if necessary.		273.311(d)	87

Bethlehem Landfill Company 100020 6/28/2022

INSPECTION REPORT - MUNICIPAL WASTE LANDFILL (Cont'd)

STATUS			s			CHAPTER	LINE
1	2	3	4	GENERAL REQUIREMENTS COMM	CITATION	ITEM	
\boxtimes				Operator submits quarterly operation report.	273.312	88	
\boxtimes				Operator submits annual operation report with fee.		273.313	89
				MINERALS AND GAS			
		\boxtimes		Gas venting and monitoring in accordance with approved plans.		273.292(a)-(d)	90
		\boxtimes		Combustible gas levels not exceeded.		273.292(e)	91
		\boxtimes		Forced gas venting if required.		273.292(f)	92
		\boxtimes		Gas recovery conducted as per approved plan and §273.293, including annual analysis.		273.293(a), (b)	93
				EMERGENCY PROCEDURES			
\boxtimes				Contingency plan implemented if there is an emergency.		273.303(a)-(c)	94
				RECYCLING			
\boxtimes				Operator shall salvage and recycle waste in accord with recycling plan. (273.196)		273.331(a)	95
\boxtimes				Salvaging and recycling controlled by operator and prevents interference within operations and prevents health hazardous nuisance.		273.331(b)	96
\boxtimes				Salvaged materials stored in an approved area or transported offsite.		273.331(c)	97
\boxtimes				Drop off center established for at least three recyclables.		273.332(a)	98
\boxtimes				Drop off center properly located, contains bins or containers, open at least 8 hours per week and 4 hours during evenings or weekends.		273.332(b), (c)	99
\boxtimes				Approved public notice of availability of drop off center availability is provided.		273.332(d)	100
\boxtimes				On or before January 15 each year, operator informs municipality in writing of weight and type of materials recycled previous year.		273.332(e)	101
				SPECIAL HANDLING AND RESIDUAL WASTES			
\boxtimes				Special handling and residual wastes disposed with prior Department approval, and in accordance with permit and Chapter 273.		273.501	102
	\boxtimes			Infectious waste disposal restrictions adhered to.		273.511(a)-(d)	103
	\boxtimes			Chemotherapeutic waste disposal restrictions adhered to.		273.512	104
	Ø			Sewage sludge co-disposal and monofill requirements followed.		273.513	105
	\boxtimes			Sewage sludge sampling requirements adhered to and sludge meets standards for control of pathogens, vectors, and odors.		273.513(c)	106
	\boxtimes			Disposal of municipal waste incineration ash in landfill or landfill cell that meets Chapter 273 requirements.		273.514(a)	107
				Ash residue disposal in dedicated landfill or landfill cell unless co-disposal in accordance with Chapter 273 (including leachability treatment).		273.514(b)	108
				Ash residue covered immediately or as approved by the Department.	273.514(c)	109	

Bethlehem Landfill Company 100020 6/28/2022

INSPECTION REPORT - MUNICIPAL WASTE LANDFILL (Cont'd)

1 2 3 4	S	TA	TU	S		CHARTER	1.1015
					GENERAL REQUIREMENTS COMMENTS ATTACHED	CHAPTER CITATION	LINE
⊠ □ □ □ Bond filed with Department. 271.312 110 Bond maintained in an amount and with guarantees as required. 271.333(b) 111 Phased deposit due date.							
Bond maintained in an amount and with guarantees as required. 271.333(b) 111	Ø				\$1.00 (2000) (1) (1) (1) (1) (1) (1) (1) (1) (1) (1	271.312	110
☑ ☐ ☐ Bond amount \$						7.0000000000000000000000000000000000000	
Phased deposit due date / / Proof of a commercial policy of liability insurances submitted to the Department as specified by 271.374. 112 Policy #HDOG72482547	\boxtimes					271.333(b)	111
Proof of a commercial policy of liability insurances submitted to the Department as specified by 271.374. Policy #HDOG72482547 Insurer (company name) ACE American Insurance Company Expiration Date: 8/1/2022							
Note					Proof of a commercial policy of liability insurances submitted to the Department		
Insurer (company name) ACE American Insurance Company Expiration Date: 8/1/2022	\boxtimes					271.374	112
Expiration Date: 8/1/2022					·	***************************************	
						1	
					П		
					П		
					П		
					n		
		F			П		



COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF WASTE MANAGEMENT

INSPECTION REPORT COMMENTS

Date of Inspection 06/28	2022	Identification Number	100020
Company/Facility/Site Nam	e _ Bethlehem Landfill Con	npany	

Comments:

The PA Department of Environmental Protection ("Department") conducted a routine complete inspection on June 28, 2022 at Bethlehem Landfill Company ("BLC"). Representing the Department from the Solid Waste Program was Mathew Vipond ("this inspector"). Phillip Garcia provided the site tour and Cody White provided this inspector with documents at the conclusion of the inspection. Weather was sunny 68°, winds NW at 5 MPH, 57% humidity.

The following Department personnel have entered the landfill since the May 25, 2022 inspection: Matt Glogowski (05/26/2022).

6/28/2022 SITE TOUR:

Prior to entering the landfill, this inspector conducted an odor patrol in the areas surrounding the landfill. A moderate intermittent garbage odor was detected from approximately 1500 feet east of the landfill entrance west to Ringhoffer Road. Phillip Garcia stated that waste was being excavated from the east side of the landfill and placed in the final cover area on the northwest side which accounted for the odors along Applebutter Road.

No excessive dust or mud was observed on Applebutter Road near the entrance to the facility.

All signage was clearly posted at the entrance.

This inspector entered the landfill at 0945 hours.

The truck wash was in operation and was being utilized by vehicles.

This inspector viewed the public disposal area on the west side of the landfill, where roll-off bins are stored. Some construction and demolition waste was observed on the ground next to one of the roll-off bins. Please ensure all municipal solid waste is deposited into roll-off bins, otherwise it becomes uncovered waste, subject to the daily cover requirements.

All roads were drivable and properly graded.

The roads throughout the landfill had been sprayed by the water truck and were dust-free.

Final cover capping activities were in progress on the northwestern side of the landfill.

Intermediate cover on the north slopes was graded and compacted. Several ruts were observed that appeared to be no more than six inches in depth.

BLC is continuing to operate the working face at SE2-AB Phase I at the eastern end of the landfill. The active face is in the same area as the May inspection, at the toe of the primary slope on the southeast area of the site. Dozers were pushing and compacting waste in the active cell. A small area of exposed waste directly west of the active waste cell was observed. BLC is reminded to apply daily cover to all areas of exposed waste, at the end of each working day, in honor of § 273.232(a)(b).

Approximately a dozen vultures were observed in and around the active waste cell.

On the south side of the landfill, grading and foundation work is being implemented by third-party contractor for the future LFG/energy plant.

BLC's flare was in operation, with a temperature of 1656°F and a flow rate of 3551 cfm.

COMPLAINT INVESTIGATIONS:

The department has not received any odor complaints since the last inspection. Odor patrols were conducted by the Department on 6/2, 6/8, 6/16, 6/23 and 6/28.

Line item #13: BLC's scale was calibrated on March 22, 2022. Overweight truck logs revealed the following number of overweight trucks:

May: 68 June: 42

Line item #17: BLC's odor patrol logs, gas data and site inspection logs were reviewed. BLC conducted 15 odor patrols in May. At the time of this inspection, BLC has conducted 11 odor patrols in June.

Line item #23: BLC's rain log in the Nuisance Minimization and Control Plan was reviewed for tracking and appears to be up to date.

Line item #24: Daily tonnages were reviewed from May 25 through June 27. There did not appear to be any exceedances of the 1800-ton daily limit. The greatest one-day tonnages for this period were:

May 26: 1531 tons June 15: 1798 tons

Line item #25-31: Daily radiation monitor checks were reviewed since the last inspection. Records appeared complete. BLC has had the following radiation hits since the May 25 inspection: 6/20/2022: I-131, disposed onsite.

Line item #51: See 6/28/22 site tour comments regarding litter in the public disposal area.

Line item #57: A Notice of Violation was issued to BLC on 4/29/20 for a violation of 25 Pa. Code §273.234(b). BLC has responded to the Notice of Violation, however the violation remains outstanding.

Line item #80: Leachate flow rates

May: 2,204,548 gallons June: 999,348 gallons

This concludes this inspection report.

Person Interviewed	Sent to Facility via Email (Signature)	Date <u>7-11-2022</u>
Inspector	Mathew Vípond	Date _7-11-2022
	(Signature)	D 0 1

Page 8 of 8

CASE: BLC ODOR PATROL SURVEY Weather Conditions: 69°F, Clandy, 90% H, NNW winds / MPH ODOR DESCRIPTION ODOR EG = Rotten Egg efacts #: 3371903 ODOR INTENSITY LFG = Landfill Gas S = Strong DURATION G = Garbage M = Moderate S = Sewage P = Persistent SL = Slight = Intermittent D = Dredge TIME SURVEY LOCATION N = None **COMMENTS & OBSERVATIONS** N = None O = Other (describe) N 10:00 N 10:01 N 10:04 N 10:05 N 10:06 N N 0:06 N 2:07 N 10:08 N 10:08 N 1013 N 10:15 Po: Applebutter to 10:18 N N 10:20 Sharry Hill Rd 12.22 500 ft last of entrance I 10:26 SL 6 N 10:30 N 10:40

Investigator: M VIPOND Date: 6/8/22 CASE: BLC
Weather Conditions: 77° F, (I) raids N/NW) 5N/PH (20°70 H, 5umy

ODOR PATROL SURVEY

				ODOR	
		ODOR		DESCRIPTION EG = Rotten Egg	
		INTENSITY	ODOR DURATION	LFG = Landfill Gas	eFacts#: 3374337
		S = Strong M = Moderate	P = Persistent	G = Garbage S = Sewage	De Millian Comment
SURVEY LOCATION	TIME	SL = Slight N = None	I = Intermittent N = None	D = Dredge O = Olher (describe)	COMMENTS & OBSERVATIONS
			IA - Molle	O - Other (describe)	COMMENTS & OBSERVATIONS
	10:05	N			
Saucon ave.	20:06				
Roberts ase.	10:09	N			
John Ton Clave.	201,10	N			
Como Ove.	10:11	N			
Mixsell ANR.	10:12	N			
Mathews Ave.	10:13	N			
Snyder are,	10:8	Ν			
School doe.	12:14	N			
Luywood are	10:15	\sim			
Riverstle Dr.	10:15	N			
Redington Rd.	10:21	·N			
Lover Laucon Ave.	10:24	N			
applebutter Rd.	20:27	SL	I	۷ .	adjacent to working face
Ringlioffer Rd.	10:29	\sim			0
Shiring Will Rd.	10:32	_ N			
applebatter El.	10:35	SL	I	6	adjacent to working face
Shyline Dr.	10:40	N			, 00

Thenesonle Rd. 10:50

Page / of /

Investigator: M. VIPAND Date: 6/16/22 CASE: BLC
Weather Conditions: 67°F, 85°6 H, winds 5 st 5 HPH, Coloredy

ODOR PATROL SURVEY

SURVEY LOCATION	TIME	ODOR INTENSITY S = Strong M = Moderate SL = Slight N = None	ODOR DURATION P = Persistent I = Intermittent N = None	ODOR DESCRIPTION EG = Rotten Egg LFG = Landfill Gas G = Garbage S = Sewage D = Dredge O = Other (describe)	Facts #: 3379244 COMMENTS & OBSERVATIONS
Shinasville Rd.	11:00	SL	1-1	S	WWTP
Saucon Ave.	14;51	Ν			
Roberts Ave.	11:04	Ŋ			
Missell Ave.	1105	N			
Adams Ave.	((06	N			
Schionbave.	11:07	N			
Nywood Ave.	1109	N			
Rosside Ald.	1110	N			
Redington Rd.	114	N			
Lance Samon Ave.	1119	N			
Applebutter Rd.	1122	M			
Ringhoffer Rd	1124	N			
Shurry Will Rd.	1126	N			
Applebatter Rd.	1130	N			
Skyline Dr.	11:36	N			
Shinersville Rd	1145	SL	I.	S	MOTP
					9

Page _____ of ____

Investigator: M. VIPOND Date: 6/23/22 CASE: BLC
Weather Conditions: Light Nation, 63° F, Light unids, 92°76 H

ODOR PATROL SURVEY

SURVEY LOCATION	TIME	ODOR INTENSITY S = Strong M = Moderale SL = Slight N = None	ODOR DURATION P = Persistent I = Intermittent N = None	ODOR DESCRIPTION EG = Rotten Egg LFG = Landfill Gas G = Garbage S = Sewage D = Dredge O = Other (describe)	efacts#:3382108 COMMENTS&OBSERVATIONS
Shimersville Rd.	1048			=	
Lower Spucon Are.	1048				
	105]				
Johnston Lie	1052				
Rdoms Rue.	1053				
Mixsell Ave.	1054				
	1055				
Snyler Ave.	1255				
Salinato Ave	636				
	1056				
Riverside Dr.	1057				
Rediration Rd	1103				
Bower Soucan Ave	1106				
Apple butter Ral	1112				
Kinghoffer Rd.	1114				
Shorry Holl Rd.	1116				
Applebutter Rd.	1120	SL	I	LFG	
Theyline Or.	1125				

Shonesville Rd. 1131

_

111/100.10	1.1001-2	CASE:	BLC
Investigator: M.VIPOND	_Date: 6/28/22_		ODOR PATROL SURVEY
Weather Conditions: 68°F, Luny	wrids NW SMPH , 57%H		ODOK PATROL SORVET

SURVEY LOCATION	TIME	ODOR INTENSITY S = Strong M = Moderate SL = Slight N = None	ODOR DURATION P = Persistent I = Intermittent N = None	ODOR DESCRIPTION EG = Rolten Egg LFG = Landfill Gas G = Garbage S = Sewage D = Dredge O = Other (describe)	Rests 本: 3383471
Shimeroirle Rd.	914				
bancon are.	914				
Roberts Roc.	917				
Inyder ave.	917				
Machines Cive.	918				
Johns Con hee.	919				
Snyder ave.	919				
Schweb loe.	920				
Logwood ane.	920				
River de Dr.	921				
Gedrigten Fd.	928				
	931				David the
appletanter Rd.	933	M	I	6	1000 ft & of entrance to entrance
Kughofer Rd.	935				
Sharry Will Rd.	938				
Coplebutter Rd.	941	SL	I	G	coodt E. of entrance to Ringlister
				5)	
		<u> </u>			

Page ____ of ___

Faulch, Amy

From:

Cody White <Cody.White@WasteConnections.com>

Sent:

Tuesday, June 28, 2022 2:21 PM

To:

Vipond, Mathew

Subject:

[External] RE: TONNAGES

ATTENTION: This email message is from an external sender. Do not open links or attachments from unknown senders. To report suspicious email, use the <u>Report Phishing button in Outlook.</u>

Matt,

Here is the data you asked for.

25-May	1,421.07
26-May	1,531.12
27-May	1,485.26
28-May	469.54
30-May	0.00
31-May	1,201.79

6,108.78

1-Jun	1,563.04
2-Jun	1,339.47
3-Jun	1,547.95
4-Jun	919.32
6-Jun	1,504.06
7-Jun	1,404.44
8-Jun	1,523.10
9-Jun	1,074.30
10-Jun	1,527.07
11-Jun	793.72
13-Jun	1,717.25
14-Jun	1,643.74
15-Jun	1,798.62
16-Jun	1,544.10
17-Jun	1,519.25
18-Jun	717.04
20-Jun	1,413.09
21-Jun	1,600.96
22-Jun	1,434.07
23-Jun	1,623.08
24-Jun	1,488.52
25-Jun	431.12
27-Jun	1,507.54

31,634.85

If you need anything else let me know.

Cheers,

Cody White

Environmental Compliance Manager

Bethlehem Landfill & Eastern Region

Office: 610.317.3200 ext. 108

Cell: 610.390.5536

Email: cody.white@wasteconnections.com



From: Vipond, Mathew <mvipond@pa.gov> Sent: Tuesday, June 28, 2022 11:36 AM

To: Cody White < Cody. White @ Waste Connections.com>

Subject: TONNAGES

WARNING: This email is from outside of Waste Connections; Exercise caution.

Hi Cody,

Could you send tonnages for May 25 through June 27?

Thanks,

Mathew Vipond | Environmental Trainee
Department of Environmental Protection | Waste Management
Bethlehem District Office
4530 Bath Pike | Bethlehem, PA 18017
Phone: 610.861.2158 | Fax: 610.861.2072
www.depweb.state.pa.us

Faulch, Amy

From:

Vipond, Mathew

Sent:

Friday, June 24, 2022 2:45 PM

To:

Faulch, Amy

Subject:

FW: [External] FW: Applebutter Road

FYI

Mathew Vipond | Environmental Trainee

Department of Environmental Protection | Waste Management

Bethlehem District Office

4530 Bath Pike | Bethlehem, PA 18017 Phone: 610.861.2158 | Fax: 610.861.2072

www.depweb.state.pa.us

From: Phillip Garcia < Phillip.Garcia@WasteConnections.com>

Sent: Friday, June 24, 2022 2:43 PM
To: Vipond, Mathew <mvipond@pa.gov>
Subject: [External] FW: Applebutter Road

ATTENTION: This email message is from an external sender. Do not open links or attachments from unknown senders. To report suspicious email, use the <u>Report Phishing button in Outlook.</u>

A few trucks have passed since the landfill owned sweeper was out on the road. I will send you some while the sweeping company is out too.

Thank you,

Phillip Garcia

Operations Manager

Bethlehem Landfill Company

Office:484-241-4643

Mobile: 484-408-5985

Fax:484-626-0600

Phillipg@wcnx.org





2335 Applebutter RD Bethlehem, PA 18015 From: Phillip Garcia < Phillip.Garcia@WasteConnections.com>

Sent: Friday, June 24, 2022 2:37 PM

To: Phillip Garcia < Phillip.Garcia@WasteConnections.com>

Subject: Applebutter









Sent from my iPhone

Faulch, Amy

From:

Phillip Garcia < Phillip.Garcia@WasteConnections.com>

Sent:

Wednesday, July 6, 2022 9:15 AM

To:

Vipond, Mathew

Cc:

Faulch, Amy; Astor Lawson

Subject:

[External] Bethlehem Truck wash

ATTENTION: This email message is from an external sender. Do not open links or attachments from unknown senders. To report suspicious email, use the <u>Report Phishing button in Outlook</u>.

Good morning All,

Just to let you all know the truck wash is getting some routine maintenance work done on it and may be out of service for the remainder of the week.

Thank you,

Phillip Garcia

Operations Manager

Bethlehem Landfill Company

Office: 484-241-4643

Mobile: 484-408-5985

Fax:484-626-0600

Phillipg@wcnx.org



2335 Applebutter RD Bethlehem, PA 18015

File Distribution:

PA DEP NERO WM File-thru A. Faulch
Facility-sent via Email PDF
Lower Saucon Township- sent via Email PDF
R. Bellas/D. Ritter (email PDF)
A. Faulch (PDF)
AQ: C. Madden/M. Bardzilouskas (e-mail PDF)
M. Glogowski (e-mail PDF)
R. Malizia (email PDF)
M. Vipond (email PDF)

Lower Saucon Township: Peter Marshall, Interim Township Manager manager@lowersaucontownship.org